



## TECHNICAL INFORMATION


**Cooker hoods**

**4-103-1611**

### **NEW CARBON FILTER AND HOLDER AT HOOD ART.NR 514440 BHP623E9X**

Due to problems with the installation of carbon filters code 432462 at hood art.nr. 514440 BHP623E9X the supplier has prepared a new code filter code 622722







Changed the mode of installation and is necessary to buy holder for carbon filter code 589874. This holder is bought only at first installation. Then replace only carbon filter. We also have set for first installation which is combined from the carbon filter and the holder code is 589878






Holder of carbon filters code 589874

## Installation of the filter and holder



Show mounting carbon filter bracket



Show mounting of carbon filter